



2016 ASN Canada FIA Briggs & Stratton Regulations**BULLETIN: 2016-04****July 13, 2016 with immediate effect**

Reference: Regulation 18. Carburetor & Intake Manifold**Add to section 18:**

Throttle cable cap on the top of the carburetor must be properly installed and secured in the fully tight position.

Reference: Regulation 25. Rocker Arms, Rocker Ball and Rocker Arm Studs**Replace 25a with:**

Rocker arms must be stock B&S part # 555711 or #797443 and may not be altered in any way. Rocker arms must be stamped with B&S Logo. Rocker arm overall length - 2.820" min.

Reference: Regulation 25. Rocker Arms, Rocker Ball and Rocker Arm Studs**Replace 25b with:**

Rocker studs must be stock, unaltered B&S part #694544 U.S. (1/4-28 thread) or #797441 Metric (M8 x 1.00 thread) and in stock location.

Rocker arm #555711(U.S.) must be used with rocker stud #694544(U.S.).

Rocker arm #797443(metric) must be used with rocker stud #797441(metric).